

## Exhibit 1

Claim No.	State	Date	Document Name	Brief Description	Document Location	Custody
11005	CT	1/27/2003	Hazardous Materials Survey Report	1.0 - Introduction	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	2.0 - Asbestos Inspection	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	2.1 - Results	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	2.3 - Conclusion	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	2.4 - Cost of Abatement	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	3.0 - Lead-Based Paint Screeing	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	3.1 - Results	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	3.2 - Conclusion	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	4.0 - PCB-Containing Fluorescent Ballasts and Mercury-Containing Lamps	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	4.1 - PCB Ballasts	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	4.2 - Mercury Lamps	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	Appendix 1 - Asbestos Sample Results and Chain of Custody (Initial Survey)	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	Appendix 2 - Asbestos Sample Results and Chain of Custody (Additional Sampling)	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	Appendix 3 - Lead Paint Testing Procedures and Equipment	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	Appendix 4 - Lead Testing Field Data Sheets	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	1/27/2003	Hazardous Materials Survey Report	Attachment 1 - Eagle Environmental Inspection Report	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	7/20/1972	Bader Company	Mono-Kote Price Protection List -- See #17	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	7/28/1972	Zonolite Memo	Revisions and Additions to Northeast District Monokote Job Price Protect List	100 Oak Street Hampton, SC	Speights & Runyan
11005	CT	4/25/2005	S&R Form	Signed Document from Building Owner that all documents have been submitted to S&R for WRG Proof of Claim	100 Oak Street Hampton, SC	Speights & Runyan